

Reserve Analysis - Property Inspection - Construction Consultants

July 28, 2016

Stanton Farms Townhouse Association, Inc. c/o KC & Associates, LLC 10108 W. San Juan Way, #210 Littleton, CO 80127

Attention: Kellie Cole

Re: Reserve Analysis: Updated 2016 Version

Dear Ms. Cole and Board of Directors:

As requested and contracted, Bradley Property Consultants, Inc. ("BPC") revised and updated the 2013 reserve analysis for Stanton Farms Townhouse Association, Inc. (Association), located in Denver, Colorado.

This updated 2016 version of the reserve analysis was performed in July 2016. The reserve analysis takes into account the condition of the property at the present time and interpolates the financial and physical condition of the Association's long term capital assets starting in 2016.

The 2013 reserve analysis was reviewed and the entire inventory list of the reserve analysis was analyzed as part of the updating process. BPC performed onsite inspections, referenced the governing documents for the Association, and reviewed the current financial position of the community. Valuable current information regarding replacements, repairs, and maintenance to the major capital assets of the Association was provided by the current president of the Association, Gerald Garfield.

The revisions and updating has brought the reserve analysis up to date with the current and expected replacement costs for the Association's major components. The proposed maintenance expectations and comments by Gerald Garfield were very valuable in producing this document. The Association may wish to consider adding or deleting some categories and possibly phasing more of the categories to spread the financial responsibilities over a number of years. The phasing can be done as a future revision to this document.

The reserve analysis is in two parts. The first section is an explanation of terms and a description of the methods involved in arriving at the data for the project. The second section starts with the reserve analysis table showing project categories and overall suggested reserve deposits. This table should be reviewed carefully and revised as necessary. The rest of the second section includes tables of reserve balances for the next 40 years, a section of graphs depicting capital expenses and reserve balances over the same 40 year period, and a table of projected capital expenses.

CHANGES AND COMMENTS FOR THE UPDATED 2016 VERSION OF THE RESERVE ANALYSIS:

Unit abbreviations used the Reserve Analysis table: SF= square feet, LF= lineal feet, SY= square yard, LS= lump sum, EA= each, REPL.= replacement, ECON.= economic

- 1. The inventory list categories from the 2013 reserve analysis were examined and aged to coordinate with their condition. Some categories were given an extended life if they had not deteriorated significantly or if they had been replaced. Some categories were expanded into more phases to spread the expected financial impact to the Association over a longer period of time. Major repairs or replacements were also considered for each category.
- 2. The Association has completed some renovation projects over the past few years. The benefits of these projects were included in the updated reserve analysis. The updated reserve analysis also attempts to identify future issues of concern to the Association.

The inventory list categories of the 2013 reserve analysis were followed and reevaluated in this 2016 updated reserve analysis. Most categories were increased in value to current cost levels, the asphalt category was expanded into five phases, and the gutter category was added to the paint and repair phases to make the inventory list more complete and compatible with the Associations expected future expenditures. The new revised reserve analysis inventory list and values are contained in the reserve analysis tables. A summary of the major changes to the reserve analysis are:

- a. The irrigation system category was increased in value to account for current replacement costs in the Denver area. The Association continues to add new environmental clocks and remove some irrigated turf in a continuing effort to reduce water costs which is one of their highest expense categories.
- b. The landscape restoration category was increased in value to an estimated spending level of \$75,000.00 every five years or \$15,000.00 per year. The Association continues to address drainage and landscape issues in adding rock beds, replacing plant material, and keeping the landscape in good condition. The Association has done a good job in adding block retaining walls to correct dangerously steep slopes behind some units.
- c. The tree trimming and removal category was increased to an estimated spending level of \$25,000.00 every five years. The very mature trees are causing root damage to the asphalt drives and the large trees within 8-10 feet of foundations should be removed before the root systems of the tress cause structural damage to the building foundations. Also, some of the very old large cottonwood trees should be considered for

removal especially if they are showing any signs of dying or weakness that would make then susceptible to falling over in a strong wind storm.

- d. The asphalt replace category was divided into five phases. The Association is addressing future asphalt replacement and regrading of the driveways and parking lots to correct deteriorating asphalt, poor drainage, and tree root damage to the asphalt. The asphalt as reached a condition of deterioration where patching does not adequately address the deteriorated condition of the asphalt. One driveway serving four buildings was regarded and replaced in 2014 with new curbs, drain pans, and asphalt. The Association intends to address and replace the other driveways in the community as funds are available. The five phases were scheduled every two years in the updated reserve study.
- e. The concrete category was increased to an estimated spending level of \$25,000.00 per year. Fallen concrete and poor drainage is a large liability for the Association.
- f. The category for drainage repairs was increased to spending \$75,000.00 every five years. The Association continues the address the poor drainage around the buildings. The poor drainage around the buildings has been an issue for this community for many years and has been referenced as a critical need in previous reserve studies. The Association is pulling out and filling sunken areas around the buildings and adding properly sloped 10 foot rock beds and longer downspouts. Irrigated turf is being removed when the new rock beds are installed which helps reduce the amount of irrigation water needed for the Association.
- g. The roof category was increased to the current replacement cost level for roofing in the Denver area. The value of replacing the Association's roofs is over one million dollars.
- h. The paint and repair categories were adjusted to add gutter repairs to the units when they are repaired and painted. The Association paints and repairs the units in seven phases. The gutter replacement category was removed from the updated reserve analysis since gutter repairs and any necessary gutter replacements are now done during the painting phases.
- 3. As noted above each of the original categories in the 2013 reserve analysis were reviewed and revised to reflect current and future replacement costs. The updated reserve analysis reflects the general condition of the capital assets as they existed at the time of this update.
- 4. The amount of reserves at the time of this update was \$430,000.00.

The work performed consisted of a review of the previous reserve study, site inspections, an interview with the property manager, and some field measurements to determine the condition and value of items for which the Association is responsible for repair and replacement. This information was used to compile and revise the reserve analysis inventory list. The reserve analysis estimates remaining economic life of the items in the inventory list, replacement costs, and prorates existing reserves to these items. The analysis then estimates future contributions to project reserves so adequate funds will be available for future repairs and replacements.

Reserve Analysis Summary and Explanation of Terms

The analysis covers the common areas and items the Association is responsible for repairing and replacing. The Association has determined these items, or inventory list, by interpretation of the Declarations and Covenants for the Association and the historical maintenance schedule on the project. The inventory list should be reviewed and modified according to the actual needs of the Association. The inventory list was listed above and is contained under the subheadings of "Common Area," and "Buildings" in the attached reserve analysis tables and graphs.

The analysis also uses the relationship of cost replacement and remaining life to determine future reserve needs. An explanation of the terms and column headings as used within the reserve analysis follows:

COMMON AREA

The Common Area covers the area around the buildings and other items that are in common use by all members of the Association. It includes fixed items within the general common area such as the irrigation system, landscape repairs, asphalt, concrete, retaining walls, and drainage repairs the commonly used areas. The capital reserves inventory list for the Association is listed the reserve analysis tables. Please refer to the inventory list and the other sections of the report for specific comments on individual reserve analysis items.

BUILDINGS

The building section describes those items directly attached to or are an integral part of the buildings. The Declarations and Covenants, as interpreted by the Association, allows for some exterior items to be replaced by the individual homeowners. Those individual homeowner items included doors, windows, window wells, air conditioners, and items inside the individual units. The Association still has architectural control over most of the exterior items, but the Association is not responsible for the replacement of every exterior item within the project. Again, please refer to the updated inventory list in the Reserve Analysis Table.

Some long-lasting items were not included in the analysis since they should survive the assumed economic life of the project. This analysis uses a 50-year useful economic life as a basis for replace-

ment items. Most items considered to have an expected life of 50 years or longer were not included in the replacement schedule. These items include building foundations and internal structural components. Please see any special notes within the analysis that pertain to items that will last 50 years or more. Most small or low cost items under \$3,000.00 were not included since these repairs and replacements tend to be funded through the annual operating budget rather than from capital reserves.

DEFINITION OF TERMS USED IN THE RESERVE ANALYSIS TABLE

Estimated Salvage Value

"Estimated Salvage Value" specifically relates to items which, by their nature, will not need total replacement at the end of their assumed economic life. The considerations affecting salvage value are its long-lasting components or parts, maintenance schedule, recent repairs or replacements, and importance to the appearance of the project. Items that directly affect the appearance and function of the project tend to be maintained more completely and more often. Hard scape items such as asphalt and concrete tend to be repaired as necessary rather than all at once. Some portions will last as long as the economic life of the project while other parts will need repairs, but not full replacement.

The "Estimated Salvage Value" identifies those items that will not need total replacement upon reaching their assumed economic life. The percentages noted on the schedule are based on our experience. They can be modified after discussions with the Board of Directors regarding areas and percentages best fitting with the overall maintenance philosophy of the project. Some items have had recent major repairs or replacements.

Replacement Costs

Replacement costs were arrived at using estimating procedures and our experience with bidding current market prices. The amounts are in current dollars and are estimates. They assume major repairs or replacements will be done all at the same time.

The actual costs for capital asset replacements may vary considerably depending on economic conditions, contract specifications, technological advances, regulatory changes, and maintenance schedules. A few adjustments for inflation were made for the replacement costs. Inflation values fluctuate and are not reliably defined. Over a long period of time, inflation is often offset by investment credits or interest earned. The varying rates and changes to the project can be reflected by periodic updates to the reserve analysis.

It is recommend updates to the reserve analysis be done on a consistent basis within a 3-5 year time period to account for any substantial changes in the capital assets and events directly affecting the cost of capital asset replacements. Such changes would include insurance settlements, natural disasters, or unknown conditions requiring significant expenditures.

Estimated Economic Life

The estimated economic life and life left are our estimates obtained from published manuals, accepted industry standards, and our experience with similar projects. The estimated life remaining for the reserve items was determined after our visual inspections and discussions with the management company. The community was constructed in 1982 and 1994. The average age of the components had to be interpreted for each inventory item since some items will age faster than others. Some items have been repaired and replaced. The major replacements and repairs are reflected in the "Remaining Economic Life" and "Estimated Salvage Value" columns in the reserve analysis tables.

The "Desired Reserve Budget," "Reserves Available," and "Annual Deposit" are arrived at after determining the estimated replacement costs and economic life span of the reserve items.

Desired Reserve Budget

The **"Desired Reserve Budget"** is the estimated amount that would have been deposited by now if the inventory items had been included in a reserve deposit schedule from the beginning of the project. Each item's estimated replacement cost is divided by its proposed economic life and then multiplied by its age to arrive at the desired reserve budget. This is a "best case" scenario to show what would have been reserved to date for each item. These figures are used to develop a percentage or proportional relationship for each item as it relates to the total "Desired Reserve Budget." The item percentage is used to distribute the present reserves and analyze future needs.

Reserves Available

The actual reserves available are distributed to each inventory item in proportion to the "Desired Reserve Budget" figures. The proportion or percentage for each item as determined by the "Desired Reserve Budget" is multiplied by the actual reserves on hand to arrive at the reserve value for each item. The reserves available for this 2016 update were \$430,000.00.

Proposed Initial Deposit

The calculated initial annual deposit for each inventory item is equal to the difference between the estimated replacement cost and the reserves available, divided by the years of life remaining for the item. This is an estimated annual deposit for each item from this time forward. The deposits attempt to achieve the desired replacement reserves in the future.

Average Annual Contribution

The calculated annual deposits required over the life of the project will fluctuate as reserves are saved and spent in the anticipated cycles. <u>The reserve analysis attempts to account for these cycles by</u> <u>calculating the average annual deposits necessary for a 40 year period</u>. In calculating your requirements, the proposed initial deposit brings your reserve balance closer to what it should be now and

the calculated average deposit lets the Association gauge what level of savings to achieve in the future.

The Association must consider that these amounts are determined as the best possible condition at a 100% funding level. To achieve an adequate reserve balance requires some long term planning. In most cases this 100% funding level is very difficult to achieve, especially if the reserves have not been analyzed for a long period of time. Most communities are doing very well if they can achieve 70-80% of the proposed annual contributions and reserve balances. A part of the planning process may be to establish a reasonable goal and attempt to reach the best result possible without extravagant demands on the homeowners.

As stated previously, it is recommended to perform periodic updates of the reserve analysis every 3-5 years to account for current replacements, changes in replacement costs, and changing interest rates. Interest earned will tend to offset inflation. Attempting to forecast into the future is tenuous at best. We believe it is preferable to make simple periodic updates to the reserve analysis and so the Association can make decisions based on the most recent information available. The reserve analysis is a working document and should be adjusted as necessary to meet the needs and desires of the Association and reflect changing conditions.

Bradley Property Consultants, Inc. performed this analysis at the request of the Board of Directors of Stanton Farms Townhouse Association, Inc. The report is intended for the Association's exclusive use and should not be used for contracting work or relied upon by any other party. The analysis reflects conditions within the property that could be examined visually and is limited to the extent of the report. The analysis is also based upon representations made by Stanton Farms Townhouse Association, Inc. in regard to existing reserve fund balances, recent replacements or repairs, and interpretation of the Declarations and Covenants for the project. While reasonable effort was made to ascertain the condition of the property and/or equipment within, it is not to be construed as a guarantee or warranty of the property or equipment therein, nor does it imply that all components will function properly on or after the date of this report. Acceptance of this report by the Association constitutes the agreement of the Association that the liability of Bradley Property Consultants, Inc. for any errors or omissions on negligent misrepresentations herein is limited to the fee paid for this report and that there shall be no liability whatsoever for incidental or consequential damages. Unless otherwise noted in the report, no sampling, testing, or dismantling of any equipment, systems or structural components of the property, other than the visual inspection, was performed. Further, no inspections or tests for soil quality or stability, asbestos, PCBs, or any other hazardous materials were undertaken nor was the quality or adequacy of the water and sewer service to the property analyzed. The inspections addressed herein were not undertaken to address any specific use or purpose contemplated by the Association other than what was stated in the report. This report does not in any way address the property's compliance with any federal, state, or local laws, rules, regulations, or ordinances.

The updated reserve analysis will provide a useful planning guide. Actual experience in replacing items may differ significantly from the estimates given. Again, it is recommended to perform periodic updates to the reserve analysis to reflect changes to current conditions.

If you have any questions or require further information, please contact our office at any time.

Very truly yours,

BRADLEY PROPERTY CONSULTANTS, INC.

Hephen M. Brakley

Stephen M. Bradley, President

Enclosures and Attachments: Updated 2016 version of the reserve analysis



RESERVE ANALYSIS UPDATED 2016 VERSION: 7-28-16

Project date: 1982-1994

Total units: 189	UNIT	QUANTITY	EST. SALVAGE VALUE %	UNIT REPL COST \$	EST. REPL COST \$	EST. ECON. LIFE YRS	EST. LIFE LEFT YRS	DESIRED RESERVE BUDGET \$	RESERVES AVAILABLE	PROPOSEI INITIAL DEPOSIT
COMMON AREA:	1								\$	\$
Sprinkler system	SF	210,798	30%	1.00	000.004					
Landscape restoration	LS	210,730	50%	1.60 75,000	236,094	35	10	168,639	57,478	17,86
Tree trimming & removal	LS	1		25,000	75,000	5	4	15,000	5,113	17,47
Community signage	LS	1		,	25,000	5	3	10,000	3,408	7,19
Timber retaining walls	SF	803		8,000	8,000	20	9	4,400	1,500	72
Block retaining walls: repair	LS	1		25.00	20,075	45	5	17,844	6,082	2,79
Asphalt: replace, Phase 1, 2014	LS	1		8,000	8,000	10	8	1,600	545	93
Asphalt: replace, Phase 2, 2017	LS	1		90,000	90,000	20	18	9,000	3,068	4,83
Asphalt: replace, Phase 3, 2019	LS	1		90,000	90,000	20	2	81,000	27,608	31,19
Asphalt: replace, Phase 4, 2021	LS			90,000	90,000	20	4	72,000	24,540	16,36
Asphalt: replace, Phase 5, 2023	LS			90,000	90,000	20	6	63,000	21,473	11,42
Asphalt: seal coat & crack fill (1/2)	SY	1		90,000	90,000	20	8	54,000	18,405	8,949
Asphalt: seal coat & crack fill (1/2)	SY	11,440		1.40	16,016	5	3	6,406	2,184	4,61
Concrete repairs: project		11,440		1.40	16,016	5	4	3,203	1,092	3,73
Maplewood fence	LS LF	1		125,000	125,000	5	4	25,000	8,521	29,120
Utility line maintenance		168		30.00	5,040	20	3	4,284	1,460	1,193
General project drainage repairs	LS	1		30,000	30,000	25	15	12,000	4,090	1,727
BUILDINGS:	LS	1		75,000	75,000	5	4	15,000	5,113	17,472
Exicellinos	1								0,1110	11,510
Roofs	SF	292,500		3.95	1,155,375	25	13	554 500		
Paint, trim, gutters: Phase 1, 2018	EA	25		1,500	37,500	2J 7	3	554,580	189,021	74,335
Paint, trim, gutters: Phase 2, 2019	EA	19		1,500	28,500	7	3	21,429	7,304	10,065
Paint, trim, gutters: Phase 3, 2020	EA	19		1,500	28,500	7	4 5	12,214	4,163	6,084
Paint, trim, gutters: Phase 4, 2021	EA	24		1,500	36,000	7	5 6	8,143	2,775	5,145
Paint, trim, gutters: Phase 5, 2022	EA	20		1,500	30,000	7	6 7	5,143	1,753	5,708
Paint, trim, gutters: Phase 6, 2016	EA	46		1,500	69,000	7	4	0	0	4,286
Paint, trim, gutters: Phase 7, 2017	EA	36		1,500	54,000	7	1	59,143	20,158	48,842
		C		1,000	54,000	/	2	38,571	13,147	20,427
CONTINGENCY		0%						1,261,599	430,000	352,490
		TOTAL REPLA	CEMENT COST		2,528,116			0	0	0
					ED RESERVES					
			12.5		DTAL RESERVES		ADIC	1,261,599	- N	
				1.	TAL NEOCHV				430,000	
							UTAL INIT	TAL CONTRIBUTION		> 352,490



RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

1588 S. Clarkson SI., Derwar, CO 80210

Phone 303 232 0252 Fax 303 232 3243

UPDATED 2016 VERSION: 7-28-16

	YEAR 2016	YEAR 2017	YEAR 2018	YEAR 2019	YEAR 2020	YEAR	YEAR	YEAR	YEAR	YEAR	YEAR
INVENTORY LIST	1	2	3	4	5	2021 6	2022 7	2023 8	2024 9	2025	2026
COMMON AREA:						1000002000000000	2010 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		<u> (((()</u>)))	10	11
Sprinkler system	75,340	93,201	111.063	128,925	1.12 1002	2010/00/00					
Landscape restoration	22,584	40,056	57,528	75,000	146,786	164,648	182,509	200,371	218,232	236.094	6,74
Tree trimming & removal	10,606	17,803	25,000		15,000	30,000	45,000	60,000	75,000	15,000	30,00
Community signage	2,222	2,944	3,666	5,000	10,000	15,000	20,000	25,000	5,000	10,000	15,00
Timber retaining walls	8,881	11,679	14,478	4.389	5,111	5,833	6,555	7.278	8,000	400	80
Block retaining walls: repair	1,477	2,409	3.341	17,276	20.075	446	892	1,338	1,784	2,231	2,67
Asphalt: replace, Phase 1, 2014	7,897	12,727		4,273	5.205	6,136	7,068	8,000	800	1,600	2,40
Asphalt: replace, Phase 2, 2017	58,804	90,000	17,556	22,386	27,215	32,045	36,875	41,704	46,534	51,363	56,19
Asphalt: replace, Phase 3, 2019	40,905		4,500	9,000	13,500	18,000	22,500	27,000	31,500	36,000	40,50
Asphalt: replace, Phase 4, 2021	32,894	57.270	73.635	90,000	4,500	9,000	13,500	18,000	22,500	27,000	31,500
Asphalt: replace, Phase 5, 2023	27,355	44,315	55,736	67,158	78,579	90,000	4,500	9,000	13,500	18,000	22,500
Asphalt: seal coat & crack fill (1/2)		36,304	45.253	54,203	63,152	72,101	81,051	90,000	4.500	9,000	
Asphalt: seal coat & crack fill (1/2)	6,794	11,405	16,016	3,203	6,406	9,610	12,813	16,016	3.203	6,406	13,50
Concrete repairs: project	4,823	8.554	12,285	16,016	3,203	6,406	9,610	12.813	16,016	3,203	9,61(
Maplewood fence	37,641	66,760	95,880	125,000	25,000	50,000	75,000	100,000	125,000		6,400
Julity line maintenance	2,653	3.847	5,040	252	504	756	1,008	1,260	1,512	25,000	50,000
General project drainage repairs	5.817	7,545	9,272	10,999	12,727	14,454	16,181	17,909	19,636	1,764	2,016
BUILDINGS:	22,584	40,056	57,528	75,000	15,000	30,000	45,000	60,000		21,363	23,091
POILDINGS;							40,000	00,000	75,000	15,000	30,000
Roofs	263,356	337,691	412,026	486,361	560,696	(7) (0.2)					
Paint, Irim, gutters: Phase 1, 2018	17,369	27,435	37,500	5,357	10,714	635,031	709,366	783,701	858,035	932,370	1.006,705
Paint, trim, gutters: Phase 2, 2019	10.247	16,332	22,416	28,500	4.071	16,071	21,429	26,786	32,143	37,500	5,357
Paint, trim, gutters: Phase 3, 2020	7,920	13,065	18.210	23,355		8,143	12,214	16,286	20,357	24,429	28,500
Paint, trim, gutters: Phase 4, 2021	7,461	13,169	18,876	23,355 24,584	28,500	4,071	8,143	12,214	16,286	20,357	24,429
aint, trim, gutters: Phase 5, 2022	4,286	8,571	12,857		30,292	36,000	5,143	10,286	15,429	20,571	25,714
aint, trim, gutters: Phase 6, 2016	69,000	9,857	12,837	17,143	21,429	25,714	30,000	4,286	8,571	12.857	17,143
Paint, trim, gutters: Phase 7, 2017	33,573	54,000	7,714	29,571 15,429	39,429	49,286	59,143	69,000	9,857	19,714	29,571
BASE RESERVES	782,490	1,026,996	1,157,093		23,143	30,857	38,571	46.286	54,000	7,714	15,429
CONTINGENCY	0	0	1,157,095	1,338,379	1,170,237	1,359,609	1,464,071	1,664,532	1,682,396	1,554,938	1,495,786
CAPITAL EXPENSES	(69,000)	(144,000)	(83,556)	0	0	0	0	0	0	0	-,
	(07,000)	(144,000)	(83,336)	(409,516)	(48,575)	(126,000)	(30,000)	(208,016)	(353,016)	(273,594)	(28,500
ANNUAL DEPOSIT	352,490	313,506	274,097	264,843	241.373	237,948	220 16-				
				201010	-41,070	431,946	230,461	230,461	225,880	225,558	214,442
TOTAL RESERVES	713,490	882,996	1,073,537	928,863	1,121,662	1.233.609	1,434,071	1 154 544			
PC, Jac., 7/2016		The second second second		suchas,	-11,002	1455,009	1,454,071	1,456,516	1,329,380	1,281,344	1,467,286



RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

1586 S. Clarkon St., Derver, CD 80210

UPDATED 2016 VERSION: 7-28-16

1566 S. Clamon St., Demer, CD 80210 Phone 303-232-0252 Fax-303-202-3243	UPDATED 2016 VERSION: 7-28-16												
INVENTORY LIST	YEAR 2027 12	YEAR 2028 13	YEAR 2029 14	YEAR 2030 15	YEAR 2031 16	YEAR 2032 17	YEAR 2033 18	YEAR 2034 19	YEAR 2035 20	YEAR 2036 21	YEAR 2037 22		
COMMON AREA:						-1000 111 125523-117-2865 4	And an	Calebra Planet Providential					
Sprinkler system	13,491	20,237	26,982	33,728	40.472	10 410							
Landscape restoration	45,000	60,000	75,000	15,000	40,473	47,219	53,964	60,710	67,455	74,201	80,94		
Tree trimming & removal	20,000	25,000	5,000	10,000	30,000	45,000	60,000	75,000	15,000	30,000	45,00		
Community signage	1,200	1.600	2,000	2.400	15,000	20,000	25,000	5,000	10,000	15,000	20,00		
Timber retaining walls	3,123	3,569	4.015	4,461	2,800	3,200	3,600	4,000	4,400	4,800	5,20		
Block retaining walls: repair	3,200	4,000	4.800	4,461	4.907	5.353	5,799	6,246	6,692	7,138	7,58		
Asphalt: replace, Phase 1, 2014	61,023	65,852	70,682		6,400	7,200	8,000	800	1,600	2,400	3,200		
Asphalt: replace, Phase 2, 2017	45,000	49,500	54,000	75,511	80,341	85,170	90,000	4,500	9,000	13,500	18,000		
Asphalt: replace, Phase 3, 2019	36,000	40,500		58,500	63,000	67,500	72,000	76,500	81,000	85,500	90,000		
Asphalt: replace. Phase 4, 2021	27,000	31.500	45,000 36,000	49.500	54,000	58,500	63,000	67,500	72,000	76,500	81,000		
Asphalt: replace, Phase 5, 2023	18,000	22,500		40,500	45,000	49,500	54,000	58,500	63,000	67,500	72,000		
Asphalt: seal coat & crack fill (1/2)	12,813	16.016	27,000	31,500	36,000	40,500	45,000	49,500	54,000	58,500	63,000		
Asphalt: seal coat & crack fill (1/2)	9,610		3,203	6,406	9,610	12,813	16,016	3,203	6,406	9,610	12.813		
Concrete repairs: project	75,000	12,813	16,016	3,203	6,406	9,610	12,813	16,016	3,203	6,406	9,610		
Maplewood fence	2,268	100,000	125,000	25,000	50,000	75,000	100,000	125,000	25,000	50,000	75,000		
Utility line maintenance		2,520	2,772	3,024	3,276	3,528	3,780	4,032	4,284	4,536	4,788		
General project drainage repairs	24,818	26,545	28,273	30.000	1,200	2,400	3,600	4,800	6,000	7,200	8,400		
BUILDINGS:	45,000	60,000	75,000	15,000	30.000	45,000	60.000	75,000	15,000	30,000	45.000		
Roofs	1,081,040	1 166 276											
Paint, trim, gutters: Phase 1, 2018	10,714	1,155,375	46,215	92,430	138,645	184,860	231,075	277,290	323,505	369,720	415.935		
Paint, trim, gutters: Phase 2, 2019	4,071	16.071	21,429	26,786	32,143	37,500	5,357	10,714	16,071	21,429	26,786		
Paint, trim, gulters: Phase 3, 2020	28,500	8.143	12,214	16,286	20,357	24,429	28,500	4.071	8,143	12,214	16,286		
Paint, trim, gutters: Phase 4, 2021	30,857	4,071	8,143	12,214	16,286	20.357	24,429	28,500	4,071	8,143	12,214		
Paint, trim, gutters: Phase 5, 2022		36,000	5,143	10,286	15,429	20,571	25,714	30,857	36,000	5,143	10,286		
Paint, trim, gutters: Phase 6, 2016	21,429 39,429	25,714	30,000	4,286	8,571	12,857	17,143	21,429	25,714	30,000	4,286		
Paint, trim, gutters: Phase 7, 2017	23,143	49,286	59,143	69,000	9,857	19,714	29,571	39,429	49,286	59,143	4,280		
BASE RESERVES		30.857	38,571	46,286	54,000	7.714	15,429	23,143	30,857	38,571	46,286		
CONTINGENCY	1,681,728	1,867,670	821,601	686,907	773,701	905,496	1,053,790	1,071,739	937,689	1,087,154	1,242,619		
CAPITAL EXPENSES	0	0	0	0	0	0	0	0	0	1,087,134	1,442,019		
EN THE ENFENCES	(28,500)	(1,232,391)	(321,016)	(99,000)	(54,000)	(37,500)	(167,516)	(319,516)	(36,000)	(30,000)	(159,000		
ANNUAL DEPOSIT	214.442		020000	111111111111111111			- the based of the second second	A CONTRACTOR	(investigation)	(sugard)	(159,000		
ANNOAL DEPOSIT	214,442	214,442	186,322	186,322	185,795	185,795	185,795	185,465	185,465	185,465	185,465		
TOTAL RESERVES	1,653,228						1			100,400	105,405		
101AL RESERVES	1,053,228	635,279	500,585	587,907	719,701	867,996	886,274	752,223	901.689	1,057,154	1,083,619		



Property Inspection • Construction Consultants 1588 S. Clarkson SI., Deriver, CO 80210

STANTON FARMS TOWNHOUSE ASSOCIATION

RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

UPDATED 2016 VERSION: 7-28-16

1568 S. Clarkson SI., Deriver, CO 80210					UPDATED	2016 VERSION	N: 7-28-16				
Phone-303 232 0252 Fax-303 232 0243	117/00/01/01/02/01/01/01										
INVENTORY LIST	YEAR 2038 23	YEAR 2039 24	YEAR 2040 25	YEAR 2041 26	YEAR 2042 27	VEAR 2043 28	YEAR 2044 29	YEAR 2045 30	YEAR 2046 31	YEAR 2047 32	YEAR 2048
COMMON AREA:											33
Sprinkler system	87,692	94,438	101,183	107,929	114,674	101 100	100.475				
Landscape restoration	60,000	75,000	15,000	30,000	45,000	121,420	128,165	134,911	141,656	148,402	155,14
Tree trimming & removal	25,000	5.000	10,000	15,000	45,000	60,000	75,000	15,000	30,000	45,000	60,00
Community signage	5,600	6,000	6,400	6,800		25,000	5,000	10,000	15,000	20,000	25,00
Timber retaining walls	8,030	8,476	8,922	9,368	7,200	7,600	8,000	400	800	1,200	1.60
Block retaining walls: repair	4,000	4,800	5,600		9,814	10,261	10,707	11,153	11,599	12,045	12.49
Asphalt: replace, Phase 1, 2014	22,500	27,000		6,400	7.200	8.000	800	1,600	2,400	3,200	4.00
Asphalt: replace, Phase 2, 2017	4,500	9,000	31,500	36,000	40,500	45,000	49,500	54,000	58,500	63,000	67,50
Asphalt: replace, Phase 3, 2019	85,500	90,000	13,500	18,000	22,500	27,000	31,500	36,000	40,500	45,000	49.50
Asphalt: replace, Phase 4, 2021	76,500		4,500	9,000	13,500	18,000	22,500	27,000	31,500	36,000	40,50
Asphalt: replace, Phase 5, 2023	67,500	81,000	85,500	90,000	4,500	9,000	13,500	18.000	22,500	27,000	31.50
Asphalt: seal coat & crack fill (1/2)	16,016	72,000	76,500	81,000	85,500	90,000	4,500	9,000	13,500	18,000	22,50
Asphalt: seal coat & crack fill (1/2)		3,203	6,406	9,610	12,813	16,016	3,203	6,406	9,610	12,813	16.01
Concrete repairs: project	12,813	16,016	3,203	6,406	9,610	12.813	16.016	3,203	6,406	9.610	
Maplewood fence	100,000	125,000	25,000	50,000	75,000	100,000	125,000	25,000	50,000	75,000	12,81
Utility line maintenance	5,040	252	504	756	1,008	1,260	1,512	1.764	2,016		100,00
General project drainage repairs	9.600	10,800	12,000	13,200	14,400	15,600	16,800	18.000	19,200	2,268	2,52
BUILDINGS:	60,000	75,000	15,000	30,000	45,000	60,000	75.000	15,000	30,000	20,400 45,000	21,60 60,00
Roofs	462,150	500 245				11					
Paint, trim, gutters: Phase 1, 2018	32.143	508,365	554,580	600,795	647,010	693,225	739,440	785,655	831,870	878.085	924,30
Paint, trim, gutters: Phase 2, 2019	20.357	37,500	5,357	10,714	16,071	21,429	26,786	32,143	37,500	5,357	10,71
Paint, trim, gutters: Phase 3, 2020	16,286	24,429	28,500	4,071	8.143	12,214	16,286	20,357	24,429	28,500	4,07
Paint, trim, gutters: Phase 4, 2021	15,429	20,357	24.429	28,500	4,071	8,143	12,214	16,286	20,357	24,429	28,50
Paint, trim, gutters: Phase 5, 2022		20,571	25,714	30,857	36,000	5,143	10,286	15,429	20.571	25,714	28,30
Paint, trim, gutters: Phase 6, 2016	8,571	12.857	17,143	21,429	25,714	30,000	4,286	8,571	12,857	17,143	
Paint, trim, gutters: Phase 7, 2017	9,857	19,714	29,571	39,429	49,286	59,143	69,000	9,857	19,714	29.571	21,42 39,42
BASE RESERVES	54,000	7,714	15,429	23,143	30,857	38,571	46,286	54,000	7,714	15,429	
CONTINGENCY	1,269,084	1,354,493	1,121,442	1,278,407	1,345,372	1,494,837	1,511,286	1,328,735	1,460,200	1.608,165	23,14
CAPITAL EXPENSES	0	0	0	0	0	0	0	0	1,400,200	1,008,105	1,765,130
SAFITAL EAFENDED	(100,056)	(418,516)	(28,500)	(118,500)	(36,000)	(169,016)	(368,016)	(54,000)	(37,500)	(28,500)	(69,516
ANNUAL DEPOSIT	185,465	185,465	185,465	185,465	185,465	185,465	185,465	185,465	198.468		and uppend
TOTAL RESERVES	1,169,028	025 075	1 000 01-		and the second second second		and proc	103,405	185,465	185,465	185,465
BPC, Jon., 7/2016	1,109,028	935,977	1,092,942	1,159,907	1,309,372	1,325,821	1,143,270	1,274,735	1,422,700	1.579.665	1,695,614

BRADLEY PROPERTY CONSULTANTS Property Inspection - Construction Consultants

STANTON FARMS TOWNHOUSE ASSOCIATION

RESERVE ANALYSIS- Reserve Balances Over Remaining Life of Components

1568 S, Clarkson SI, Derwer, CO 80210 Phone 503 231-0252 Fax 303 232-3243 UPDATED 2016 VERSION: 7-28-16

INVENTORY LIST	YEAR 2049 34	YEAR 2050 35	YEAR 2051 36	YEAR 2052 37	YEAR 2053 38	YEAR 2054 39	YEAR 2055 40
COMMON AREA:				88.000 ANN 88.000		ana ang kang kang kang kang kang kang ka	*****************
Sprinkler system	161,893	168,639	175,384	182,130	188,875	195,621	
Landscape restoration	75,000	15.000	30,000	45.000	60,000	75,000	202,366
Tree trimming & removal	5,000	10,000	15,000	20,000	25,000	75,000 5,000	15,000
Community signage	2,000	2,400	2,800	3,200	3,600		10,000
Timber retaining walls	12,937	13,383	13,829	14,276	14,722	4,000	4,400
Block retaining walls: repair	4,800	5,600	6,400	7,200	8,000	15,168	15,614
Asphalt: replace, Phase 1, 2014	72,000	76,500	81,000	85,500		800	1,600
Asphalt: replace, Phase 2, 2017	54,000	58,500	63,000	67,500	90,000	4,500	9,000
Asphalt: replace, Phase 3, 2019	45,000	49,500	54,000	58,500	72,000 63,000	76,500	81,000
Asphalt: replace, Phase 4, 2021	36,000	40,500	45,000	49,500		67,500	72,000
Asphalt: replace, Phase 5, 2023	27,000	31,500	36,000	40,500	54,000	58,500	63,000
Asphalt: seal coat & crack fill (1/2)	3,203	6,406	010,00	12,813	45,000	49,500	54,000
Asphalt: seal coat & crack fill (1/2)	16,016	3,203	6,406	9.610	16,016	3,203	6,406
Concrete repairs: project	125,000	25,000	50,000	75.000	12,813	16,016	3,203
Maplewood fence	2.772	3,024	3,276		100,000	125,000	25,000
Utility line maintenance	22,800	24,000	25,200	3,528	3,780	4,032	4,284
General project drainage repairs	75,000	15,000	30,000	26,400	27,600	28,800	30,000
BUILDINGS		12.000	30,000	45,000	60,000	75,000	15,000
Roofs	970,515	1,016,730	1,062,945	1,109,160	1155.075		
Paint, trim, gutters: Phase 1, 2018	16,071	21,429	26,786		1,155,375	46,215	92,430
Paint, trim, gutters: Phase 2, 2019	8,143	12,214	16,286	32,143	37,500	5,357	10,714
Paint, trim, gutters: Phase 3, 2020	4.071	8,143	12,214	20,357	24,429	28,500	4,071
Paint, trim, gutters: Phase 4, 2021	36,000	5,143	10,286	16,286	20,357	24,429	28,500
Paint, trim, gutters: Phase 5, 2022	25,714	30,000	4,286	15,429	20,571	25,714	30,857
Paint, trim, gutters: Phase 6, 2016	49,286	59,143	4,286	8,571	12,857	17,143	21,429
Paint, trim, gutters: Phase 7, 2017	30,857	38,571	46,286	9,857	19,714	29,571	39,429
BASE RESERVES	1,881,079	1,739,528	1,894,993	54,000	7,714	15,429	23,143
CONTINGENCY	0	1.733,328	1,094,993	2,011,458	2,142,924	996,498	862,447
CAPITAL EXPENSES	(327,016)	(30,000)	(69,000)	0 (54,000)	0 (1,331,891)	0 (319,516)	0 (58,500
ANNUAL DEPOSIT	185,465	185,465	185,465	185,465	185,465	185,465	185,465
TOTAL RESERVES	1,554,063	1,709,528	1,825,993	1,957,458	811,033	676,982	803,947



1588 S. Clarkoon St., Danver, CO 80210

STANTON FARMS TOWNHOUSE ASSOCIATION

RESERVE ANALYSIS- Projected Capital Expenses By Year

UPDATED 2016 VERSION: 7-28-16

INVENTORY LIST	2016 1	2017 2	2018	2019 4	YEAR 2020 5	YEAR 2021 6	YEAR 2022 7	YEAR 2023 8	YEAR 2024	YEAR 2025	YEAR 2026
COMMON AREA:					ononininininininininininini	and a second	9999- 7 -24 <u>13-194</u> 1	<u></u> 9		10	11
Sprinkler system	Ö	0	0	745							
Landscape restoration	0	0	0	0	0	0	0	0	0	236,094	
Tree trimming & removal	0	0	25,000	75,000	0	0	0	0	75,000	0	-
Community signage	0	0	0	0	0	0	0	25,000	0	0	-
Timber retaining walls	0	0	0	0	0	0	0	0	8.000	0	-
Block retaining walls: repair	0	0	0	0	20,075	0	0	0	0	0	
Asphalt: replace, Phase 1, 2014	0	0	0	0	0	0	0_	8,000	0	0	
Asphalt: replace, Phase 2, 2017	0	90,000	0	0	0	0	0	0	0	0	
Asphalt: replace, Phase 3, 2019	0	0	0	0	0	0	0	0	0	Ő	
Asphalt: replace, Phase 4, 2021	0	0	0	90,000	0	0	0	0	0	0	
Asphalt: replace, Phase 5, 2023	0	0	0	0	0	90,000	0	0	0	0	
Asphall: seal coat & crack fill (1/2)	0	0	16.016	0	0	0	0	90,000	0	0	
Asphalt: seal coat & crack fill (1/2)	0	0	and the second second	0	0	0	0	16,016	0	0	
Concrete repairs: project	0	0	0	16,016	0	0	0	0	16,016	0	
Maplewood fence	0	0	5,040	125,000	0	0	0	0	125,000	0	
Utility line maintenance	0	0	a second a second se	0	0	0	0	0	0	0	
General project drainage repairs	0	0	0	0	0	0	0	0	0	0	
BUILDINGS		U.	0	75,000	0	0	0	0	75.000	0	1
Roofs	0	0	0	0							
Paint, trim, gutters: Phase 1, 2018	0	0	37,500	0	0	0	0	0	0	0	(
Paint, trim, gutlers: Phase 2, 2019	0	0	0	28,500	0	0	0	0	Ŭ	37,500	
Paint, trim, gutters: Phase 3, 2020	0	0	0	28,500	0	0	0	0	0	0	28,500
Paint, trim, gutters: Phase 4, 2021	0	0	0	0	28,500	0	0	0	0	0	t and t
Paint, trim, gutters: Phase 5, 2022	0	0	0	0	0	36,000	00	0	0	0	0
Paint, trim, gutters: Phase 6, 2016	69,000	0	0	0	0	0	30,000	0	0	0	0
Paint, trim, gutters: Phase 7, 2017	0	54,000	0	0	0	0	0	69,000	0	0	0
Capital Expense	69,000	144,000	83,556	409.516	0	0	0	0	54,000	0	0
			00,000	407,510	48,575	126,000	30,000	208,016	353,016	273,594	28,500

1

BPC, Inc., 7/2016



1588 5. Clarkson St., Derwer, CO 50210

STANTON FARMS TOWNHOUSE ASSOCIATION

RESERVE ANALYSIS- Projected Capital Expenses By Year

UPDATED 2016 VERSION: 7-28-16

Phone-300-232-0252 Fax-303-232-3243	UPDATED 2016 VERSION: 7-28-16												
INVENTORY LIST	YEAR 2027 12	YEAR 2028 13	YEAR 2029 14	YEAR 2030 15	YEAR 2031 16	YEAR 2032 17	YEAR 2033 18	YEAR 2034 19	YEAR 2035 20	YEAR 2036 21	YEAR 2037 22		
COMMON AREA:							ala an an tha		1999-1999-1999-1999-1999-1999-1999-199	1999 -1 999-1999	11111		
Sprinkler system	0	0	0	0	0	0	0						
Landscape restoration	0	0	75,000	0	0	0	0	75,000	0	0			
Tree trimming & removal	0	25,000	0	0	0	0	25,000		0	0			
Community signage	0	0	0	0		0	0	0	0	0			
Timber retaining walls	0	0	0	0	0	0	0	0	0	0			
Block retaining walls: repair	0	0	0	0	0	0	8,000	0	0	0			
Asphalt: replace, Phase 1, 2014	0	0	0	0	0	0		0	0	0			
Asphalt: replace, Phase 2, 2017	0	0	0	0	0	0	90,000	0	0	0			
Asphalt: replace, Phase 3, 2019	0	0	0	0	0	the second se	0	0	0	0	90,000		
Asphalt: replace, Phase 4, 2021	0	0	0	0	0	0	0	0	0	0			
Asphalt: replace, Phase 5, 2023	0	0	0	0		0	0	0	0	0			
Asphalt: seal coat & crack fill (1/2)	0	16.016	0	0	0	0	0	0	0	0	(
Asphalt: seal coat & crack fill (1/2)	0	0	16.016			0	16,016	0	0	0	(
Concrete repairs: project	ő	0	125,000	0	0	0	0	16,016	0	0	(
Maplewood fence	0	0	0		0	0	0	125,000	0	0	(
Utility line maintenance	0	0	0	0	0	0	0	0	0	0	(
General project drainage repairs	0	0		30,000	0	0	0	0	0	0	(
BUILDINGS:	U.	IJ	75,000	0	0	0	0	75,000	0	0	ć		
Roofs	0	1,155,375	0	0	2	_							
Paint, trim, gutters: Phase 1, 2018	0	0	0	0	0	0	0	0	0	0	C		
Paint, trim, gutters: Phase 2, 2019	0	0	0	0	0	37,500	0	0	0	0			
Paint, trim, gutters: Phase 3, 2020	28,500	ő	0	0	0	0	28,500	0	0	0	(
Peint, trim, gutters: Phase 4, 2021	0	36,000		0	0	0	0	28,500	0	0	6		
Paint, trim, gutters: Phase 5, 2022	0	30,000	20,000	0	0	0	0	0	36,000	0	0		
Paint, trim, gutters: Phase 6, 2016	0	0	30,000	0	0	0	0	0	0	30,000	0		
Paint, trim, gutters: Phase 7, 2017	0	0	0	69,000	0	0	0	0	0	0	69,000		
Capital Expense	28,500	1,232,391	0	0	54,000	0	0	0	0	0	0		
	20,000	1,432,391	321,016	99,000	54,000	37,500	167,516	319,516	36,000	30,000	159,000		

BPC, Inc., 7/2016

BRADLEY PROPERTY CONSULTANTS Property Inspection • Construction Consultants

1588 S. Clarkson SI., Derwar, CO 60210

STANTON FARMS TOWNHOUSE ASSOCIATION

RESERVE ANALYSIS- Projected Capital Expenses By Year

1588 S. Clarkson St., Derver, CO 60210 Phone 303 232 4252 Fex-303-232-3243			UPDATED 2016 VERSION: 7-28-16										
INVENTORY LIST	YEAR 2038 23	YEAR 2039 24	YEAR 2040 25	YEAR 2041 26	YEAR 2042 27	VEAR 2043 28	YEAR 2044 29	YEAR 2045 30	YEAR 2046 31	YEAR 2047	YEAR 2048		
COMMON AREA:					Static Station in the second			10.1112 11111 1111111111		32	Ŋ		
Sprinkler system	0	0	0										
Landscape restoration	0	75.000	0	0	0	0	0	0	0	0			
Tree trimming & removal	25,000	0	0	0	0	0	75,000	0	0	0			
Community signage	0	0	0	0	0	25,000	0	0	0	0	25.00		
Timber retaining walls	0	0		0	0	0	8,000	0	0	0	-23,00		
Block retaining walls: repair	0	0	0	0	0	0	0	0	0	0			
Asphait: replace, Phase 1, 2014	0	0		0	0	8,000	0	0	0	0			
Asphalt: replace, Phase 2, 2017	0	0	0	0	0	0	0	0	0	0	1		
Asphalt: replace, Phase 3, 2019	0	90,000	0	0	0	0	0	0	0	0			
Asphalt: replace, Phase 4, 2021	0	90,000	0	0	0	0	0	0	0	0			
Asphalt: replace, Phase 5, 2023	0	0	0	90,000	0	0	0	0	0	0			
Asphalt: seal coat & crack fill (1/2)	16,016	0	0	0	0	90,000	0	0	0	0	1		
Asphalt: seal coat & crack fill (1/2)	10,010	16.016	0	0	0	16,016	0	0	0	0			
Concrete repairs: project	0	the state of the s	0	0	0	0	16,016	0	0	- hereite -	16,01		
Maplewood fence	5,040	125,000	0	0	0	0	125,000	0	0	0			
Utility line maintenance		0	0	0	0	0	0	0	0	0			
General project drainage repairs	0	0	0	0	0	0	0	0	0	0			
BUILDINGS:	0	75,000	0	0	0	0	75,000	0	0	0			
Roofs	0	0	0										
Paint, trim, gutters: Phase 1, 2018	0	37,500	0	0	0	0	0	0	0	0	(
aint, trim, gutters: Phase 2, 2019	0	0	28,500	0	0	0	0	0	37,500	0			
Paint, trim, gutters: Phase 3, 2020	0	0	and the second sec	0	0	0	0	0	0	28,500			
Paint, trim, gutters: Phase 4, 2021	0	0	0	28,500	0	0	0	0	0	0	10.00		
aint, trim, gutters: Phase 5, 2022	0	0	0	0	36,000	0	0	0	0	0	28,500		
Paint, trim, gutters: Phase 6, 2016	0	0	0	0	0	30,000	0	0	0	0			
Paint, trim, gutters: Phase 7, 2017	54,000	0	0	0	0	0	69,000	0	0	0	6		
Capital Expense	100,056	418.516	0	0	0	0	0	54,000	0	8	0		
and a set of power and the set of	1001050	410,510	28,500	118,500	36,000	169,016	368,016	54,000	37,500	28,500	69,516		

BPC, Inc., 7/2016




RESERVE ANALYSIS- Projected Capital Expenses By Year

1588 S. Clarkson St., Derwor, CO 80210

UPDATED 2016 VERSION: 7-28-16


1588 S. Clarkson St., Derver, CO 80210		UPDATED 2016 VERSION: 7-28-16									
Phone-303-232-0252 Fax-303-232-3243											
INVENTORY LIST	YEAR 2049 34	YEAR 2050 35	YEAR 2051 36	YEAR 2052 37	YEAR 2053 38	YEAR 2054 39	YEAR 2055 40				
COMMON AREA:							**************				
Sprinkler system	0	0	0	0	0	0					
Landscape restoration	75,000	0	0	0	0	75,000					
Tree trimming & removal	0	0	0	0	25,000						
Community signage	0	0	0	0	23300	0					
Timber relaining walls	0	0	0	0	0	0					
Block retaining walls: repair	0	0	0	0	8,000	0					
Asphalt: replace, Phase 1, 2014	0	0	0	0	90.000	0	(
Asphalt: replace, Phase 2, 2017	0	0	0	0	90,000	0	(
Asphalt: replace, Phase 3, 2019	0	0	0	0	0	0	.(
Asphalt: replace, Phase 4, 2021	0	0	0	0	0	0					
Asphalt: replace, Phase 5, 2023	0	0	0	0	0	0	(
Asphalt: seal coat & crack fill (1/2)	0	0	0	0	16.016	0	(
Asphalt: seal coat & crack fill (1/2)	16.016	0	0	0	the state of the s	0	(
Concrete repairs: project	125,000	0	0	0	0	16.016	(
Maplewood fence	0	0	0	0	0	125,000	(
Utility line maintenance	0	0	0	0	0	0	(
General project drainage repairs BUILDINGS:	75,000	0	0	0	0	0 75.000	30,000 0				
Roofs	0	0	0	0	1,155,375						
Paint, trim, gutters: Phase 1, 2018	0	0	0	0	37,500	0	0				
Paint, trim, gutters: Phase 2, 2019	0	0	0	0	37,500	0	0				
Paint, trim, gutters: Phase 3, 2020	0	0	0	0	0	28,500	0				
Paint, trim, gutters: Phase 4, 2021	36,000	0	0	0	0	0	28,500				
Paint, trim, gutters: Phase 5, 2022	0	30,000	0	0		0	0				
Paint, trim, gutters: Phase 6, 2016	0	0	69.000	0	0	0	0				
Paint, trim, gutters: Phase 7, 2017	0	0	0	54,000	0	0	0				
Capital Expense	327,016	30,000	69,000	54,000	1.331.891	0 319,516	58,500				

BPC, htt., 7/2016




1

HPC, Inc., 7/2016




2

BPC. Inc., 1/2010



10947, brs., 7/2014



4

8PC.bs., 7/2016

i.