



Unfinished Wood trim installed by Maintanance and allowed to decompose



Roof leaks coming out of everything but drains in Townhomes



Fire Building 50 that had roof section replaced is now leaking



President's house Can mount Dish incorrectly as per the Rules and Regulations and has wrong Colored Windows




Building 50 that had fire is found to have bulb shorting out and heating up–Smells like melted plastic–Level 1 North side



Building 50 that had fire is found to have Front
Fire door installed incorrectly with major air leaks
plastic-North side
South side doors do not close correctly



Building 50 that had fire is found to have a Dead
Smoke Detector–South End Top Floor



Building 50 window was never finished and is allowed to decompose



Club House window is caulked but not painted and allowed to Decompose



Building 50 should have these Rail Road ties
ripped out and thrown away



Garages could be painted but are allowed to Rust