

Community Preservation Committee

Affordable Housing Roosevelt Senior Housing

Handicapped Accessibility

This common walkway leading to the rubbish disposal area has been uprooted by tree roots causing the walkway to be unstable and exposure to risk of personal injury and is especially difficult for residents in wheelchairs

Before



After

