



Condo Doors without handles
Notice the Finish is shot



Water Leaking out of everything but the drains in the Town homes, Frozen drain pipes



Example of a Homeowner who Painted and caulked his garage -Looks Great and helps the Beautification of the area



Example of a Homeowner who Painted and caulked his garage



Structure Damage from water



Old Rusty Mailboxes that have not been replaced in over 30 years



Maintenance personnel riding on grassy areas with there toys



Garbage Dump Area Ceiling water damage from not finishing Job



Garbage Dump Area Ceiling water damage from not finishing Job



Frozen pipes at town homes



Scrub brush not removed in 30 years and allowed to get out of control all around this complex