



Hot Tub Gets New Heater

Many thanks to Dave Radford our dedicated maintenance technician who went above and beyond the call of duty to get the hot tub up and running so quickly.



We ordered the new heater and received it on Wednesday February

29th and on Thursday Dave removed the old heater and had the new one installed and working. Next time you see him around Broadway Station, be sure to stop him and say thanks!

Sincerely,
Broadway Station
Owners Association
Board of Directors

P.S. Here are captions for the photos:

Image 1 - spa heater before removal (front side).

Image 2 - same (rear side) Notice unit position on pad (pad was set wrong way initially).

Image 3 - same (rear side).

Image 4 - same (bottom view) that is the fire box you see through the rusted out shield panel.

Image 5 - old unit removed, surrounding area cleared, ground leveled, pad positioned correctly + supply/return lines bypassed to allow filter operation .

Heater Photos

